



# Tampersils Size Selection Guide

## Straight Sided Containers


Measure the widest point over which the seal must pass, then add 2mm. For example, if the diameter of the cap is 50mm you should choose a seal of 52mm diameter.

Choose a length to suit the purpose but remember the 10% shrinkage which takes place in this direction when the seal is fully dry

## Conical Containers and More Complex Shapes



In these cases it is important that the difference between the smallest diameter and the largest diameter to be covered by the seal, should not exceed 25%.

If you are unsure, you should send us a detailed drawing of the product you want to seal and we will assist you in finding the correct size.



*Don't delay – get in touch now!*

 01785 250 123  01785 220 104

 [sales@valleynorthern.com](mailto:sales@valleynorthern.com)  [www.valleynorthern.com](http://www.valleynorthern.com)